

## **Factors Affecting Rate of Moisture Migration**

Factors that affect the rate of moisture migration during drying include:

- Temperature (usually maintained between 50-65°F),
- Relative humidity (usually maintained between 65-72% to prevent the surface from drying out too fast leading to case hardening),
- Air velocity, and
- Air distribution and direction (want < 2 air changes per minute)