

Process Deviation

A process deviation occurs whenever the actual process is less than the process schedule or when any critical factor does not comply with the requirements for that factor as specified in the process schedule, or when a retort operating parameter (e.g., vent schedule) is not met.